

**Illinois Commerce Commission
Pipeline Safety
Field Trip Report**

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Exit Meeting Contact: Dallas Jett	Total Man Days: 4
Pipeline Safety Representative(s): Kevin Hecker, Matt Smith	
Company Representative to Receive Report: Michael Fuller	<u>Emailed Date:</u>
Company Representative's Email Address: mfuller2@ameren.com	09/17/2013

Inspection Summary

Inspection Type	Location	ICC Analyst	Inspection Unit(s)	Man Day(s)	Inspection Date(s)	Contact(s)
Standard Inspection - Field Audit	Marion	Matt Smith Kevin Hecker	Marion	4	8/13/2013, 8/15/2013	Dallas Jett

Statement of Activities

On August 13 and 15, 2013, a field audit was conducted at Ameren Illinois, in Marion, Illinois, to determine compliance with applicable IL Adm. Codes and the Code of Federal Regulations adopted via IL Adm. Part 590.

Staff observed the installation of new steel main along Morgan Avenue and the welding of a tie-in at the intersection of Morgan at Atchison on 8/13/13. On 8/15/13, staff observed a 2" plastic main fusion to a transition fitting at the same intersection.

ISSUE(S) FOUND:

NO ISSUES FOUND.

ISSUE(S) CORRECTED:

NO ISSUES CORRECTED.

NOTICE OF AMENDMENT(S) FOUND:

NO NOAs FOUND.

NOA(S) CORRECTED:

NO NOAs CORRECTED.

NOTICE OF PROBABLE VIOLATION(S) FOUND:

NO NOPVs FOUND.

NOPV(S) CORRECTED:

NO NOPVs CORRECTED.